

MODEL: GM63B

Vibration Meter Instruction Manual



(€ ②



S.andard:Q/GMY 002-2016 Version: GM63B-EN-03

CONTENTS

1. Before use	
○ Check-up	(01)
○ Introduction	(02)
O Features	
Specifications	
Olagram of the product	
O LCD displays	(06)
2. Operation	
Battery installment	(07)
Selecting probe tip	
 Connection between handle and main s 	init (09)
 Turn on the unit and check-up battery 	(10)
 Select measurement mode 	(11)
Select high/low frequency	(12)
O Measuremen t	
Maxmum value measurement	(15)
Temperature unit change	(16)
O Vibration conversion chart	(17)
Contact resonance in acceleration mea	
	(40)

3. Other items

O Attentions	(20)
○ Warranty & Maintenance	(21

1. Before use

Check-up

Carefully unpack your kit and ensure that you have the following items. In case that any item is missing or if you find any mismatch or damage, promptly contact your dealer.

Ö	Main unit	1PCS
Ü	Detector handle	1PCS
O	9V Alkaline battery	1PCS
Ö	Instruction manual	1PCS
Ö	Detector probe accessorg (L)	1PCS
0	Detector probe accessorg (S)	1PCS
	(Equiped on the main unit)	
O	Magnetic probe	1PCS
O	PP packing box	1PCS

Introduction

This product adopts piezoelectric effect of artificial polarized ceramic for design. It is suitable for monitoring of all kinds of vibrating mechanical facility, specially the vibration measurement of rotating and reciprocating machinery. The unit can measure acceleration, velocity and displacement, which is widely used in mechanical manufacture, electric power metallurgy and general aviation etc. Field.

Features

- ULCD display measurement result and conditions directly
- Measures acceleration (m/s[∓] peak), velocity (mm/s ms), and displacement (mm p-p)
- O Selective vibration characteristic
- Uses hi- sense of vibration sensor, measuring accurately
- Equipped two probes (S and L) to adapt the different measurement requirement
- O Provides a magnetic probe to fit the condition uneasy hold on by hand
- O Low battery indication
- Auto turn off function
- ULCD back light function
- Maximum value hold function
- O Temperature unit C /F selection

Specifications


Technical parameter	Technical specification
Vibration pickup	Piezoelectric ceramic accole: ometer (she
Measurement range	0.1-199.9m/s ¹ peak
of acceteration	
Measurement range	0.1~199.9mm/s rms
of velocity	
Measurement range	0.001~1.999nwn p-p
of displacement	Velocity and hisplacement range is limited
30	acceleration199.9m/s'
Measurement accuracy	±5%±2digits
Measurement Irequency	1011z~1KHz (LO) 1KHz~15KHz (III)
range of acceleration	
Measurement frequency	1011z~1KHz (LO)
range of velocity	
Measurement frequency	10Hz- 1KHz (LO)
range of displacement	
Displays update cycle	1 seconds
LCD display	3 1/2 digits display
	AC output 2 V prak (display full scale)
Single output	Load impedance 10K 0 or more earphones
	can be connected
Power supply	9V hattery
Stand-by current	≤15 µ A
Operating current	≤2SmA
Rattery life	20 H. continuous use
Auto power off function	Turns off automatically after 65 seconds
CD backinght function	7 seconds
Operating temperature i	AD KALE T.
Operating humidity rang	80-90%RH

72x35x145mm

Low battery indication 6.4V±0.2V

Dimensions

Diagram of the unit



- 1. Handle connector (with directionality)
- 2. LCD display.
- 3. MEAS ON/Off / measure button, press for turn on.
 In measuring procedure, press for measuring, release for hold the reading.
- 4. HI/LO Frequency character selection bottom.
 (For acceleration)
- 5. MAX Maximum value locks botton.
- 6. C/ F Temperature unit interchange botton.
- 7. A/V/D Measuring mode (Acceleration/ Velocity/ Displacement) select bottom.
- 8. Handle on/off/ measure button, press for turn on. In measuring procedure, press for measuring, release for hold the reading.
- 9. Detector tip (Selective between "S"/"L" and Magnetic probe.



Note

Above key function descriptions just are simple introduction, for details please read operation instructions part in this manual.

LCD display



- 1). Imi: Battery mark shows current residual battery power.
- 2). Dynamic bar graph display measuring Icon.
- 3). LO: low frequency symbol. (10Hz~1Hz)
- 4). Measured value display.
- 5). MAX: The maximum value.
- 6). Temperature and maximum value display.
- 7). E Temperature unit display, "F" for the Celsius scale, "E" for the Fahrenheit scale.
- 8).mm/s²: When measuring acceleration, LCD will display acceleration unit "m/s²"

When measuring velocity, LCD will display velocity unit "mm/s"


When measuring displacement, LCD will display displacement unit "mm"

- 9). 1KHz: 1kHz indication.
- 10). HI: High frequency symbol. (1kHz~15kHz)
- 11). The symbol of the range of the measuring value
- 12). 🁸 : Backlight icon, the back light will be active for 7 seconds upon the button operations.

2. Operation instructions:

Battery installment

- a. Grip tightly the unit body with your left hand; hold down the battery door with your right hand thumb to open it according to the arrow referring direction:
- b. Insert the 9V battery into battery compartment, note the battery polarity, and then close the battery door, as shown in following figure:



Select Probe tip

This vibration meter is designed to fit the different measurement requirements as follows. \aleph

A. With tip probe S: It provides good response and reproducibility over a wide range.

As the following figure.



B. With probe tip L: Suitable for narrow object or special objects to obtain quick response as the following at figure.


C. With Magnetic probe: Suitable for measurement in cases where flat Ferric object to the stable measurement, as the following figure.



D. Without probe tip: In this condition, best high-range response is achieved (10Hz to 15kHz), but planar contact with the measurement object is required as the following picture.

Detector installment

Attention to the directionality of the socket.




Plug in/out method:

Before use, plug in the handle to main unit's socket the same direction, there a lock sound to ensure the plug is locking.


When plug out, the user must push the metal upwards to release the lock status and pull out.

Turn on the unit and check-up battery

1. Press the on the main unit or on the handle to turn on, as shown in following figure:



2. After the entire screen displays for 1 second, the default state is acceleration mode, if on the LCD displays the symbol or please promptly replace the battery, as shown in following figure:



Selecting measurement mode

1. Press" Select the measuring mode, the default status is accelerometer measure "m/s", as following picture:





3. Press the key one more times to selecting displacement mode "mm", as following picture.



Hi/Lo frequency selection

Hi frequency "HI" is only for acceleration measure mode. Press "HI/LO" key to select the high frequency measure or low frequency measure.

As following picture:







High frequency measuring is only for acceleration measure mode.

Measurement

Depending on the material physical value and vibratory source's vibration frequency, select the corresponding measurement mode (Acceleration/ Velocity/ Displacement) and frequency (HI/LO), holding press the main unit or handle's "button, press the handle sensor head against the surface with 500g~ 1kg vertical force, the measuring value will be shown on LCD display, release the button to lock the value. Show as below picture:









When press "key again, the current locking value will be cancelled, a new measurement will be preformed.



Caution

- Probe tlp "S" is apply to measure high/ low frequency range vibration.
- 2. Probe tip "L" is only for low frequency measure, when measure acceleration, if the frequency is over 1 kHz, please change Probe tip "S" for measurement.
- When measurement mode from acceleration in high frequency mode to velocity or displacement mode, the unit will change to low frequency automatically.
- 4. Auto power- off for 1 minute
- LCD packlight will auto- off if there is no further operation in 7 seconds.

Maximum value measurement

After turn on, press " (MAX)" to enter maximum value mode. In maximum value measuring status, the current vibration data and the maximum value will display on LCD display. Show as below:



When press " (MAX) " key again, the maximum measure status will cancelled, and change to temperature display status.


Temperature unit change

In operation, press ""C/"F" to select ""
Celsius scale and ""
Fahrenheit scale., show as below:







Vibration conversion chart



Contact resonance in acceleration measurement: (worked with FFT signal analyzer)

(Measured with FFT Signal analyzer)





3.Other items

Attentions

↑ Warning

When making measurements on exposed rotating parts or power train parts of machinery, proceed with utmost care to prevent accidents due to getting caught in the machinery.

If the unit shook excessively, the receiver may produce extremely high sound pressure that hurts human ear, be careful in process of using the signal output plug.

Warranty & Maintenance

Maintenance:

- 1. Replacement and upkeep of battery:
 - a. After power on, if an icon imappears on the LCD, you need to replace the battery immediately, for details please refer figures and contents on page 9 of this manual.
 - Remove the battery from the unit if it is not required for extended periods of time in order to avoid damage to the battery compartment and the erosion resulting from a battery leakage.
- 2. Do not store or use the unit in following circumstances:
 - a. Splashes of water or high levels of dust.
 - b. Air of high salt or sulphur content.
 - c. Air mixed with other gases or contents.
 - d. High temperature or humidity (above50°€, 90%,) or direct sunlight.
- 3. Do not disassemble the unit or attempt any internal alterations.
- Never use alcohol or diluents to clean the housing for doing that will especially erode the LCD surface; just clean the unit lightly as needed with little clean water

Warrity:

- 1. About relative warranties please read warranty card.
- We disclaim any liability due to: client's transportation damages; incorrect use or operation; manipulation, alterations or repair attempts; without warranty card, invoice



Specific Declarations;

Our company shall hold no any responsibility resulting from using output from this product as an direct or indirect evidence. We reserves the right to modify product design and specification without notice.